

FIELD INSPECTION REPORT

Date of Inspection :	18/12/2020	District:	Muzaffarpur
Division :	MU2 - West	Length (km):	0.524 km
Name of the Road:	Indalaya Ramabhogi Ke char TO Indalaya Kumaon-pale		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	(MM689)
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U ✓
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	S/U ✓
d)	Road Camber	S/U ✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. (B.T)	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U ✓
c)	Condition of railings/slab/approach for Bridges	S/SRI/U ✓
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	U

Overall Rating :

Satisfactory (S)	U
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	-

(Signature)

NAME:

Shankar Kumar

DESIGNATION:

J.F