

FIELD INSPECTION REPORT

Date of Inspection :	20-12-2020	District:	NALANDA
Division :	HARNAUT	Length (km):	0.50 km.
Name of the Road:	NALANDA NOORSARI ROAD @ Tyari Baidan to MILKIPAR.		
Scheme/Programme:	MAINTENANCE	Construction.	
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance ✓		
Work is a case of:	✓ New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	✓ S/U	
b)	Condition of Surfacing	✓ S/U	
c)	Riding Quality	✓ S/U	
d)	Road Camber	✓ S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓	
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ✓	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts other's	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges Deparment's	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓	
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Q. Kumar
20-12-2020
(Signature)

NAME: AJAY KUMAR VERMA.

DESIGNATION: JUNIOR Engineer.