

FIELD INSPECTION REPORT

Date of Inspection : 17/12/2020		District : East Champaran
Division : Chakia		Length (Km):
Name of the Road : PMGSY Road Jamunia to Yadav to la jamunia via Madhyvidhaly		
Scheme/Programme : MAINTENANCE		Km : Jamunia.
Package No.:		Road ID No.:
Status of the Project :	Ongoing/Completed/Under Maintenance	
Work is a case of :	New Connectivity/Up Gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	N/A
b)	Condition of Surfacing	- SRI -
c)	Riding Quality	- SRI -
d)	Road Camber	- SRI -
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	- NO -
f)	Contraction Joints provided or not (CC Pavement)	- Yes -
g)	Compaction of flank/slope & raincuts if any	—
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	- SRI -
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	- SRI -
c)	Condition of railings/slab/approach for Bridges	- SRI -
3.	Road Furniture	
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained	- SRI -
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :	Satisfactory (S)	
	Satisfactory but requires improvement (SRI)	- SRI -
	Unsatisfactory (U)	

Remarks:- Bush cutting; Surface damage; CD painting required.

NAME : *[Signature]*
17/12/2020
JG
DESIGNATION :

(Signature)



Shot on vivo Z1 Pro
Vivo AI camera

2020.12.23 11:53

Scanned by CamScanner