

# FIELD INSPECTION REPORT

Date of Inspection : 22.12.2020

Division : Chakia

District : East Champaran

Name of the Road : Kankali Mahadali Basti Ramayodhya Thakur

Scheme/Programme :

ghar Bhander hai ke ghar via Baramha Sahu

Package No.:

Road ID No.:

Status of the Project :

Ongoing/Completed/Under Maintenance

Work is a case of :

New Connectivity/Up Gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	'S'
b)	Condition of Surfacing	'S'
c)	Riding Quality	'S'
d)	Road Camber	'S'
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	'S'
f)	Contraction Joints provided or not (CC Pavement)	'S'
g)	Compaction of flank/slope & raincuts If any	
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	'S'
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	
c)	Condition of railings/slab/approach for Bridges	
3.	Road Furniture	
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained	'S'
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)

Satisfactory but requires improvement (SRI)

Unsatisfactory (U)

'S'

Zakir  
22.12.2020

(Signature)

NAME :

DESIGNATION :