

FIELD INSPECTION REPORT

Date of inspection: 22-12-2020		District: East Champaran	
Division: B.D (w). Chakia		Length (Km): 2.40	
Name of the Road: From Tanki chauri Silahard to Bedihari madhabpur, Malhah Tola.			
Package No.:		Road ID No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up Gradation/ Maintenance	
Sl No	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition		S
b)	Condition of surfacing		SRJ
c)	Riding Quality		S
d)	Road Camber		S
e)	Whether free from defects such as visible cracks, exposed aggregate in case of CC Pavement.		
f)	Contraction Joints provided or not (CC Pavement)		Yes
g)	Compaction of Bank/slope & raincuts if any		SRJ
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts		—
c)	Condition of railings/slab/approach for Bridges		—
3.	Road Furniture		
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained		S
4.	Compliance History		
a)	Status of ATR's & any others		—

Overall Rating :

Satisfactory (S)

Satisfactory but requires improvement (SRJ)

Unsatisfactory (U)

SRJ

Inspected
22/12/20
J.E.

(Signature)

NAME :

DESIGNATION :