

FIELD INSPECTION REPORT

Date of Inspection : 22.12.2020		District : East Champaran	
Division : Chakia		Length (Km): 2.653	
Name of the Road : Mehli Katakha 110 Path se chalonagon			
Scheme/Programme :			
Package No.:		Road ID No.:	
Status of the Project :		Ongoing/Completed/Under Maintenance	
Work is a case of :		New Connectivity/Up Gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S	
b)	Condition of Surfacing	S	
c)	Riding Quality	S	
d)	Road Camber	S	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	yes/no	
f)	Contraction Joints provided or not (CC Pavement)	yes	
g)	Compaction of flank/slope & raincuts if any		
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	yes/no	
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts		
c)	Condition of railings/slab/approach for Bridges		
3.	Road Furniture		
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained	yes	
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :	Satisfactory (S)	(S)
	Satisfactory but requires improvement (SRI)	
	Unsatisfactory (U)	

Signature
22.12.2020

(Signature)

NAME :

DESIGNATION :