

FIELD INSPECTION REPORT

Date of Inspection : 17/12/2020		District : East Champaran	
Division : Chakia		Length (Km): 3.0 km.	
Name of the Road : PMGSY path kurva to harpur Naya tola.			
Scheme/Programme : PMGSY		MAINTENANCE	
Package No.:		Road ID No.:	
Status of the Project :		Ongoing/Completed/Under Maintenance	
Work is a case of :		New Connectivity/Up Gradation/ Maintenance	
Sl. No.	Parameters to be checked		Remarks
1,	Pavement		
a)	Road Junction condition		- S -
b)	Condition of Surfacing		- S -
c)	Riding Quality		- S -
d)	Road Camber		- S -
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes.
f)	Contraction Joints provided or not (CC Pavement)		Yes.
g)	Compaction of flank/slope & raincuts if any		- SRI -
2,	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		- SRI -
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts		- SRI -
c)	Condition of railings/slab/approach for Bridges		-
3,	Road Furniture		
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained		-SRI-
4,	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :	Satisfactory (S)	
	Satisfactory but requires improvement (SRI)	SRI
	Unsatisfactory (U)	

Remarks:- Compaction of flank & bush cutting required.

NAME :

fbw
17/12/2020
JC

(Signature)

DESIGNATION :