

FIELD INSPECTION REPORT

Date of Inspection : 11-12-2020		District: Dombivga	
Division : Dombivga		Length (km): 2.801 km	
Name of the Road: Raghonath PMS Road to Telga Rohan			
Scheme/Programme: MAINTENANCE			
Package No.:	MMS	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U 5	
b)	Condition of Surfacing	S/U 5	
c)	Riding Quality	S/U 5	
d)	Road Camber	S/U 5	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No 14	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No 15	
g)	Compaction of flank/slope & raincuts if any	Yes/No 16	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SR/U 5	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR/U 5	
c)	Condition of railings/slab/approach for Bridges	S/SR/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No 17	
4.	Compliance History		
a)	Status of ATR's & any others	N/A	

Overall Rating :

Satisfactory (S)	(S)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Note:

Road Damaged in Flood, Submerged till two months approx. Temporary restoration done also Permanent Restoration work going on.

(Signature) 12-2020

NAME: Vivek Kurey

DESIGNATION: A/E