## FIELD INSPECTION REPORT

Date of Inspection: 26/12/20			District: Kaimo	11	
Division: Mohania District: Kainun  Length (km): 0.900 kM					
Name of the Road: Chaprang from TOA TO GOVESTER.  Scheme/Programme: MAIN WNANCE PMGSX					
The state of the s					asx
Package	No.: BROST	2355	Road Id No.:		
Status of the Project: Ongoing/Completed/Under Maintenance					
Work is a case of: New Connectivity/Up gradation/ Maintenance					
Sl. No.		Parameters to be checked			Remarks
1.	Pavement	Pavement			
a)	Road Junction	ction condition			√S/U
b)	Condition of Surfacing				√8/U
c)	Riding Quality				<b>S</b> /U
d)	Road Camber				<b>√</b> s/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				Xes/No
f)		ontraction Joints provided or not (CC Pavement)			Xes/No
g)	Compaction of flank/slope & raincuts if any				Nes/No
2.	Cross Drainag	ge			
a)	Condition of head walls in Hume pipe culverts including its painting				/S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts				√s/sri/U
c)	Condition of railings/slab/approach for Bridges				√S/SRI/U
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				Fes/No
4.	Compliance History				
a)	Status of ATR's & any others				NO
ope					101
Overall Rating : Sa		Satisfactory (S)		n n	151
			quires Improvement (S	RI)	
Unsatisfactor					
		9			

(Signature)26/12/20

NAME: Md. Jamil Abul Hessay (Acst. Engy).