FIELD INSPECTION REPORT

Date of In	spection: 26	112/2020	District: Kainu	1	
Date of Inspection: 26/12/2020 District: Kaima Division: Mohania Length (km): 0.90			NKM		
Name of t	he Road: Cha	ta Brass	To Kanha Tola	etaliniste (s.). estelezent euro, po	and the state of t
Scheme/Programme: MAINTENANCE				PM 434	
Package	No.: BROS	R 356	Road Id No.:		
magazine and the second of the second of	the Project:		eted/Under Maintenance	angi kanakan kanan kanan yang	and the second second
Work is a	case of:		ty/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked		14	Remarks	
1.	Pavement				
a)	Road Junction condition			✓S/U	
b)	Condition of Surfacing				√ 57U
e)	Riding Quality			✓S/U	
d)	Road Camber			✓S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				✓Yes/No
0	Contraction Joints provided or not (CC Pavement)				Yes/No
g)	Compaction of flank/slope & raincuts if any				Yes/No
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			✓S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts				₩/SRI/U
e)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				✓es/No
4.	Compliance History				
a)	Status of ATR's & any others				No
Overa	Il Rating		. (6)		100
0,010		Satisfactory	but requires Improvement (5	RD	(ی)
		Unsatisfactory	TOO IN		

(Signature)

NAME: Md. Jamil Abulttessay (Acst. Engg)