FIELD INSPECTION REPORT

ate of In	spection: 28/12/	020	District: Kaftham		
lame of		T02 7	To Mammiya		
cheme	heme/ Programme:		MAINTENANCE		
			Road ID No.	1073	
Package	the Project: Onging/Completed/Under Maintenance				
· · · · · ·			ectivity/ Up Gradation/ Maintenance		
Nork is a	case of:		ameters to be Checked	Remarks	
SI.No					
	Pavement			S/U	
a)	Road Junction Condition			\$/U	
b)	Condition of Surfacing			\ 3 /U	
c)	Riding Quality			S/U	
d)	Road Camber Whether free from defects such as visible cracks, exposed aggregates in case of			Yes/No	
e)				Yes/No	
. 4	CC Pavement Contraction Joints provided or not (CC Pavement)			Yes/No	
f)	Compaction of flank/slpoe & raincuts if any				
g)				S/SRI/U	
2	Cross Drainage Condition of headwalls inn Humepipe culverts including its painting Condition of headwalls inn Humepipe culverts in RCC culverts			S/SRI/U	
a)	Condition of headwards in Francisco Condition of Abutment & Wings walls, Slab in RCC culverts Condition of Abutment & Wings walls, Slab in RCC culverts			S/SRI/U	
b)	Condition of Abuthent & Wings Condition of railings/slabs//approach for Bridges				
c)	Condition of railings/stabs// approcess			Yes/No	
3	t the formation / cautionary Board/ No.				
a)	Whether sign boards/informatory/caddonary Pavement road markings are provided and maintained.				
4	Compliance History				
a)	Status of ATR & any others			S	
		0-4-6	(6)		
Overall	Grading:	Satisfacto	ory but requires Improvement(SRI)		
		Unsatisfac	otony (1)		
		Ulisatistat	(Signature)	670	
			() () () () () () () () () () () () () (
	Amvendra No	4 Thales	(Signature)	, y. di	
Name:	Amvenus		그 가면 존전한 사람이 보다 됐습니다.		

Scanned by CamScanner