FIELD INSPECTION REPORT

Date of Inspection: .12.2020			District: Kishanganj		
Division: Kishanganj-1			Length(km):		
Name o	f the Road: 1044	-Tol to Kada	olata,		
	/Programme:				
Package	e No.:	2	Road Id No.: 21205802120		
Status of the Project: Ongoing/Cor			leted /Under Maintenance V		
Work is	a case of:	New Connectivi	ity/ Up gradation / Maintenance		
51. No	Parameters to be checked		Remarks		
1.	Pavement			S/U	
a)	Road Junction Condition			∪S/U	
b)	Condition of Surfacing			US/U	
c)	Riding Quality			√\$/U	
d)	Road Camber			LS/U	
e)	Whether free from defects such as visible cracks, exposed aggregates			Yes/No	
	in case of CC Pavement.				
f)	Contraction Joints Provided or not (CC Pavement)			∠Yes/No	
g)	Compaction of flank / shop & raincuts if any			1 Yes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its Painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, slab in RCC culverts			S/SRI/U	
c)	Condition of railings/Slab/approach for Bridges			S/SRT/U	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m			Yes/No	
-	stones/Pavement road markings are provided and maintained				
4.	Compliance History				
a)	Status of ATR'	s & any others	Hot	ATR.	

Overall Rating:

Satisfactory(S)	"S"
Satisfactory but requires Improvement (SRI)	
Unsatisfactory(U)	

(Signature)

NAME: Sanjeev Kumar Paswan J.E, RWD, Terhagachh