

FIELD INSPECTION REPORT

Date of Inspection: .12.2020	District: Kishanganj	
Division: Kishanganj-1	Length(km):	
Name of the Road: LO 21 to Fulbari namakars.		
Scheme/Programme:	PMGSY.	
Package No.:	Road Id No.:	
Status of the Project:	Ongoing/Completed /Under Maintenance ✓	
Work is a case of:	New Connectivity/ Up gradation / Maintenance ✓	
S1. No	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction Condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints Provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank / shop & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its Painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCC culverts	✓S/SRI/U
c)	Condition of railings/Slab/approach for Bridges	✓S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	Not ATR

Overall Rating :

Satisfactory(S)	"S"
Satisfactory but requires Improvement (SRI)	
Unsatisfactory(U)	

NAME: Sanjeev Kumar Paswan
J.E, RWD, Terhagachh

Sanj
17/12/2020 -
(Signature)