1810- 1105:201

FIELD INSPECTION REPORT

Date of Inspection: 29.12.2020			District: Kishanganj		
Division: Kishanganj-1			Length(km): 0.860		
Name of the Road: PM USY Road tachubari to Maya for					
Scheme/Programme:					
Package No.: Road Id No.: 2			Road Id No.: 2120581803	25	
			npleted /Under Maintenance		
			y/ Up gradation / Maintenance		
S1. No		<u>Parameters</u>	s to be checked	Remarks	
1.	Pavement			~57U	
a)	Road Junction Condition			45/U	
b)	Condition of Surfacing			~5/U	
c)	Riding Quality			.S/U	
d)	Road Camber			<i>-</i> 8/U	
e)	Whether free f	rom defects such	as visible cracks, exposed aggregates	Yes/No	
	in case of CC Pa	avement.			
f)	Contraction Joints Provided or not (CC Pavement) Yes/N			У e s/No	
g)	Compaction of flank / shop & raincuts if any Yes/N			Yes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its Painting		-S∕SRI/U		
b)	Condition of Abutment & Wing walls, slab in RCC culverts			-S/SRI/U	
c)	Condition of railings/Slab/approach for Bridges			S/SRI/U	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m			Yes/No	
	stones/Pavement road markings are provided and maintained				
4.	Compliance His	story			
a)	Status of ATR's	& any others		NOT ATP	

Overall Rating:

Satisfactory(S)	(3)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory(U)	

(Signature) 17 2020

NAME: Umesh Kumar Singh J.E, RWD, Kishanganj