

FIELD INSPECTION REPORT

Date of Inspection: 22-12-2020 District: East Champaran

Division: Road & Civil Engineering Length (km): 3.645

Name of the Road: Lohi Pithi Road, In District, East Champaran

Package No. Road ID No.

Status of the Project: Ongoing/Completed/Under Maintenance

Work in a case of: New Connectivity/Up Gradation/ Maintenance

Sl. No. Parameters to be checked Remarks

1. Parameters

a) Road Junction condition S

b) Condition of surfacing S

c) Riding Quality S

d) Road Camber S

e) Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.

f) Contraction Joints provided or not (CC Pavement) Yes

g) Compaction of Bank slope & raincuts if any S

2. Cross Drainage

a) Condition of head walls in Hume pipe culverts including its painting S

b) Condition of Abutment & Wing walls, Slab in RCC Culverts S

c) Condition of raftings/slab/approach for Bridges

3. Road Furniture

a) Whether sign board/informatory/cautionary Board/4m & 200m Stones/Pavement road markings are provided and maintained S

4. Compliance History

a) Status of ATR's & any others

Overall Rating : Satisfactory (S) S
Satisfactory but requires improvement (SRI)
Unsatisfactory (U)

NAME: Ujjwal Kumar

DESIGNATION: J.E.

Signature: 24/12/20