

FIELD INSPECTION REPORT

Date of Inspection : 21/12/20	District : East Champaran
Division : Chotia	Length (Km): 2.00 km
Name of the Road : Jamsini Chand Passa to Yadav Tola	
Scheme/Programme : CITSNY	
Package No.:	Road ID No.:
Status of the Project :	Ongoing/Completed/Under Maintenance
Work is a case of :	New Connectivity/Up Gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1,	Pavement	
a)	Road Junction condition	S
b)	Condition of Surfacing	U
c)	Riding Quality	U
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	No
f)	Contraction Joints provided or not (CC Pavement)	Yes
g)	Compaction of flank/slope & raincuts if any	No
2,	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	Yes
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	-
c)	Condition of railings/slab/approach for Bridges	-
3,	Road Furniture	
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained	Yes
4,	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :	Satisfactory (S)	
	Satisfactory but requires improvement (SRI)	
	Unsatisfactory (U)	U

Note:- Some Damage due to flood.

(Signature) 23/12/20

NAME :

DESIGNATION :