FIELD INSPECTION REPORT

Date of	Inspection: 25/13	Joso District: katéhan	
Name o	f Road:	RED ROad Ghass Told to Risks makedalit	tola
Scheme	Programme:	MAINTENANCE	
Package	e No.	Road ID No.	
	the Project:	Onging/Completed/Under Maintenance	A Company of the
	a case of:	New Connectivity/ Up Gradation/ Maintenance	
SI.No	a case on	Parameters to be Checked	Remarks
1	Pavement		
a)	Road Junction Condition		√8/U
b)	Condition of Surfacing		
c)	Riding Quality		
d)	Road Camber		√8/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slpoe & raincuts if any		Yes/No
2	Cross Drainage		
a)	Condition of headwalls inn Humepipe culverts including its painting		
b)	Condition of Abutment & Wings walls, Slab in RCC culverts		
c)	Condition of railings/slabs//approach for Bridges		
3	Road Furniture		
	Whether sign boards/informatory/cautionary Board/Km & 200m stone/ Pavement road markings are provided and maintained.		Yes/No
4	Compliance History		
a)	Status of ATR & any others		
verall Grading: Satisfactory (S)			SRI
14.2		Satisfactory but requires Improvement(SRI)	
		Unsatisfactory (U)	
		Jun Alsto	∞
	Amore Don 100 At	TTO Para DO	
ame: egisnati	Amrendra Nath	(Signature)	