FIELD INSPECTION REPORT

Date of	Inspection:	17.12.20	District: Para	
ivisio	n: Dans	2	Length (km): 2.332 Km	
Name o	of the Road: As	hopus Lakhani	Digha Road Meas Hol	i mussion so
, cucint	or rogramme:	MAINTENANCE		
Packag			Road Id No.:	
	of the Project:		Under Maintenance	
	s a case of:		gradation/ Maintenance	39
Sl. No.		Parameters to b	e checked	Remarks
1.3	Pavement		国公共 主义。	放保主义强
a)	Road Junction	condition		S/Ų
b)	Condition of Surfacing			√S/₩
c)	Riding Quality •			SIV
. d)	Road Camber			✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of tlank/slope & raincuts if any			Yes/No
2.	Cross Drainag	se de la companya de	total	War San
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furnitur	e		
a)	Whether sign stones/Pavemen	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
4.0	Compliance IIi	story	的人的 "我是这	
a)	Status of ATR's	& any others		

Overall Rating

Satisfactory (S)	<u>C</u>
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Dirah Choedhay
DESIGNATION: A!