

FIELD INSPECTION REPORT

Date of Inspection : 22.12.2020

Division : Chakia

District : East Champaran

Name of the Road : Bhimalpur Bazar to Balua.

Length (Km): 1.405 Km.

Scheme/Programme :

Package No.:

Road ID No.:

Status of the Project :

Ongoing/Completed/Under Maintenance ✓

Work is a case of :

New Connectivity/Up Gradation/ Maintenance

Sl. No.

Parameters to be checked

Remarks

1,

Pavement

a)

Road Junction condition

(S)

b)

Condition of Surfacing

(SRT)

c)

Riding Quality

(S)

d)

Road Camber

(S)

e)

Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.

Yes/No

f)

Contraction Joints provided or not (CC Pavement)

Yes

g)

Compaction of flank/slope & raincuts if any

2,

Cross Drainage

a)

Condition of head walls in Hume pipe culverts including its painting

Yes

b)

Condition of Abutment & Wing walls, Slab in RCC Culverts

c)

Condition of railings/slab/approach for Bridges

3,

Road Furniture

a)

Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained

Yes

4,

Compliance History

a)

Status of ATR's & any others

Overall Rating :

Satisfactory (S)

Satisfactory but requires improvement (SRI)

Unsatisfactory (U)

(SRI)

22.12.2020
J E

NAME :

(Signature)

DESIGNATION :