

FIELD INSPECTION REPORT

Date of inspection: 22-12-2020
 Division: Road (W) Division Chitkin
 District: East Champaran
 Length (Km): 2.744
 Name of the Road: Tihuliga Buri Hajar K. Jha. Se. to Modah Tala Via Anwarul Tala Tala
 Scheme No.:
 Package No.:

Status of the Project: Ongoing/Completed/Under Maintenance
 Road ID No.:

Work is a case of: New Connectivity/Up Gradation/ Maintenance

Sl. No	Parameters to be checked	Remarks
1.	Pavement	S
a)	Road Junction condition	S
b)	Condition of surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	
f)	Contraction Joints provided or not (CC Pavement)	Yes
g)	Compaction of Bank/slope & raincuts if any	
2.	Grass Drainage	—
a)	Condition of head walls in Hume pipe culverts including its painting	Yes
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	—
c)	Condition of railings/slab/approach for Bridges	—
3.	Road Furniture	
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained	Yes
b)	Compliance History	—
a)	Status of ATR's & any others	

Overall Rating : Satisfactory (S)
 Satisfactory but requires improvement (SRI)
 Unsatisfactory (U)

Signature
 22/12/20
 J.C

NAME :
 DESIGNATION :

(Signature)