



FIELD INSPECTION REPORT

Date of Inspection: 22-12-2020		District: East Champaran	
Division: R.W.D.(W) Chakia		Length (Km): 2.310	
Name of the Road: R.F. Path Beddara Madhara Shikharadi to Samulak Jharia Vinidwan			
Package No.:		Road ID No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up Gradation/ Maintenance	
Sl. No	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S	
b)	Condition of Surfacing	S	
c)	Riding Quality	S	
d)	Road Camber	S	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		
f)	Contraction Joints provided or not (CC Pavement)	Yes	
g)	Compaction of flank/slope & raincuts if any	S	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	SRI	
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	—	
c)	Condition of railings/slab/approach for Bridges	—	
3.	Road Furniture		
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained	S	
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :	Satisfactory (S)	
	Satisfactory but requires improvement (SRI)	SRI
	Unsatisfactory (U)	


 NAME: Uttam Prasad
 DESIGNATION: JE


 (Signature) 24/12/20