

FIELD INSPECTION REPORT

Date of Inspection: 22.12.2020 District: East Champaran
 Division: RWD (44) Dhanu Bazar C.P. area Length (Kms): 3.089 K.M.
 Name of the Road: PWD Road, Wapin Pali Narasimha Chandra to Dababouya
 Submittal Programme: MAINTENANCE
 Package No.: Road ID No.:

Status of the Project: Ongoing/Completed/Under Maintenance
 Work is a case of: New Connectivity/Up Gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S
b)	Condition of surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	
f)	Contraction Joints provided or not (CC Pavement)	S
g)	Compaction of flank/slope & rainouts if any	S
2.	CROSS DRAINAGE	S
a)	Condition of head wall & in some case culverts including its painting	
b)	Condition of Abutment & Wing walls, Slab in RCC Culvert	S
c)	Condition of railing/slab/approach for Bridges	=
3.	Road Furniture	
a)	Whether sign board/informatory/cautionary Board/Km & 100m Stones/Pavement road markings are provided and maintained	S
b)	Compliance History	
a)	Status of ATR's & any others	-

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement: (SRI)	
Unsatisfactory (U)	

Sup. Engr
22/12/20

(Signature)

NAME :

DESIGNATION :