## FIELD INSPECTION REPORT

Date of	Inspection: 29.1	2.2020	District: Kishanganj		
Division: Kishanganj-1			Length(km): 1.000 Cm		
Name of the Road: PMInSV to Marry on to li					
Scheme/Programme: (ITSNY					
Package No.: Road Id No.: 21205801898					
			eted /Under Maintenance		
Work is a case of: New Connectivity/ Up gradation / Maintenance					
S1. No	Parameters to be checked			Remarks	
1.	Pavement			S/U	
a)	Road Junction Condition			LSHU	
b)	Condition of Surfacing			_S/U	
c)	Riding Quality			S/U	
d)	Road Camber			J8/U	
e)	Whether free from defects such as visible cracks, exposed aggregates  Yes/No				
	in case of CC Pavement.				
f)	Contraction Joints Provided or not ( CC Pavement)			Yes/No	
g)	Compaction of flank / shop & raincuts if any			Yes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its Painting			∠S/SRI/U	
b)	Condition of Abutment & Wing walls, slab in RCC culverts			_S/SRI/U	
c)	Condition of railings/Slab/approach for Bridges			8/SRI/U	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m			Yes/No	
	stones/Pavement road markings are provided and maintained				
4.	Compliance His				
a)	Status of ATR's & any others			MOTATR	

## Overall Rating:

Satisfactory(S)	VES/S)
Satisfactory but requires Improvement (SRI)	1.
Unsatisfactory(U)	

(Signature) 9/12/2427

NAME: Umesh Kumar Singh J.E, RWD, Kishanganj