

FIELD INSPECTION REPORT

Date of Inspection : 27/11/20	District: Purmā
Division : Dhemdaha	Length (km): 2.925 km.
Name of the Road: Chankra choda to chandradi Satsang Bhawan	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	/ S/U
b)	Condition of Surfacing	/ S/U
c)	Riding Quality	/ S/U
d)	Road Camber	/ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	/ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	/ Yes/No
g)	Compaction of flank/slope & raincuts if any	/ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	/ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	/ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	/ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	1
Satisfactory but requires Improvement (SRI)	1 SRI
Unsatisfactory (U)	1

NAME:

Shailendra Kumar
AIE Dhemdaha

(Signature)
27/11/20