

FIELD INSPECTION REPORT

Date of Inspection : 25-12-2020		District: Madhubani	
Division : Jaynagar		Length (km): 0.435 Km	
Name of the Road: Dakshinwari Tola se Bhagwanthpatti			
Scheme/Programme: MAINTENANCE			
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked		Remarks
1. Pavement			
a)	Road Junction condition		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No
2. Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting		S/SR/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SR/U
c)	Condition of railings/slab/approach for Bridges		S/SR/U
3. Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No
4. Compliance History			
a)	Status of A.T.R.'s & any others		

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	✓
Unsatisfactory (U)	

NAME: Chubangan Rahul

DESIGNATION: JE


25/12/2020
(Signature)