

FIELD INSPECTION REPORT

Date of Inspection : 14.12.2020	District: W. Champaran
Division : Bettiah	Length (km): 0.60 K.M
Name of the Road: Bairathpur Border to Tribhuvanpaly	
Scheme/Programme:	MAINTENANCE
Package No.: GTSNY	Road Id No.: 31808801826
Status of the Project:	Ongoing/Completed/Under Maintenance UNDER Maint
Work is a case of:	New Connectivity/Up gradation/ Maintenance New Connectivity

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S ✓S/U
b)	Condition of Surfacing	S ✓S/U
c)	Riding Quality	S ✓S/U
d)	Road Camber	S ✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes ✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes ✓Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes ✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/A S/SRI/U
c)	Condition of railings/slab/approach for Bridges	N/A S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	1 S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


14.12.20
(Signature)

NAME: SUNIL KUMAR

DESIGNATION: J-E