

## FIELD INSPECTION REPORT


Date of Inspection: 29/12/2020 District: Kishanganj  
 Division: Kishanganj - 1 Length(km): 1.000  
 Name of the Road: Bhebhra Harijan to 101A to Losy Kochadham  
 Scheme/Programme: GTNLSY  
 Package No.: Road Id No.:  
 Status of the Project: Ongoing/Completed /Under Maintenance ✓  
 Work is a case of: New Connectivity/ Up gradation / Maintenance

S1. No	Parameters to be checked	Remarks
1.	<b>Pavement</b>	✓S/U
a)	Road Junction Condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints Provided or not ( CC Pavement)	✓Yes/No
g)	Compaction of flank / shop & raincuts if any <i>raincuts</i>	Yes/No ✓
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its Painting	S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCC culverts	S/SRI/U
c)	Condition of railings/Slab/approach for Bridges	NA S/SRI/U
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory(S)	-
Satisfactory but requires Improvement (SRI)	RJ
Unsatisfactory(U)	-

NAME: RANJEET KUMAR

  
 29/12/20  
 (Signature)  
 RJ