

FIELD INSPECTION REPORT

Date of Inspection : 22.12.2020		District : East Champaran
Division : Chakia		Length (Km): 1.6201km
Name of the Road : 40900 Jyoti Bada to Chintamani via Bahadur guz talu.		
Scheme/Programme :		
Package No.:		Road ID No.:
Status of the Project :	Ongoing/Completed/Under Maintenance	
Work is a case of :	New Connectivity/Up Gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks
1,	Pavement	
a)	Road Junction condition	15'
b)	Condition of Surfacing	15 SR'
c)	Riding Quality	15'
d)	Road Camber	15'
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes.
f)	Contraction Joints provided or not (CC Pavement)	Yes.
g)	Compaction of flank/slope & raincuts if any	Yes.
2,	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	No
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	
c)	Condition of railings/slab/approach for Bridges	
3,	Road Furniture	
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained	Yes.
4,	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :	Satisfactory (S)	
	Satisfactory but requires improvement (SRI)	15 SR'
	Unsatisfactory (U)	

22.12.2020
JE

(Signature)

NAME :

DESIGNATION :