FIELD INSPECTION REPORT

NACORA

Date of Inspection: 17:12:20		7.12.20	District: Patra		
Division: Danapus			Length (km): 0.750 Km		
Name of	the Road: Do	tu What is	athur pwp party Ke Ashor	W Gram K	
		MAINTENANC	E Ke Ran	vindle Rai	
Package		1	Road Id No.:		
	the Project:		eted/Under Maintenance		
Work is	a case of:	New Connectivit	ly/Up gradation/ Maintenance	~	
Sl. No.		Parameters	s to be checked	Remarks	
* 1	Pavement-	Page 1		Maria A	
a)	Road Junction	condition		✓S/U	
b)	Condition of Surfacing			✓S/IJ	
c)	Riding Quality			✓S/U	
d)	Road Camber			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		. Xes/No ~		
f)	Contraction Jo	oints provided or n	ot (CC Pavement)	Yes/No	
g)	Compaction o	f tlank/slope & rai	ncuts if any	Yes/No ~	
2.	Cross Draina	ge			
a)	Condition of I	lead walls in Hum	e pipe culverts including its painting	· S/SRI/J·	
b)	Condition of A	\butment & Wing	walls, Slab in RCC culverts	S/SRI/J	
c)	Condition of r	Condition of railings/slab/approach for Bridges		S/SRI/U	
3.	Road Furniture			" "家	
a)	Whether sign stones/Paveme	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No	
4.	Compliance I	listory			
a)	Status of ATR	's & any others			

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

12 22 20

NAME:

Dinesh chuelny

DESIGNATION:

AE