

FIELD INSPECTION REPORT

| Date of Inspection : | 17/12/2020 | District: | Kaipur |
|------------------------|--|--------------|----------|
| Division : | Kaipur Bhabhug | Length (km): | 0.750 Km |
| Name of the Road: | Lo3 to Anan Mahato tola | | |
| Scheme/Programme: | MAINTENANCE | | |
| Package No.: | 117/0754 | Road Id No.: | |
| Status of the Project: | Ongoing/Completed/Under Maintenance | | |
| Work is a case of: | New Connectivity/Up gradation/ Maintenance | | |
| Sl. No. | Parameters to be checked | Remarks | |
| 1. | Pavement | | |
| a) | Road Junction condition | ✓ S/U | |
| b) | Condition of Surfacing | ✓ S/U | |
| c) | Riding Quality | ✓ S/U | |
| d) | Road Camber | ✓ S/U | |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | ✓ Yes/No | |
| f) | Contraction Joints provided or not (CC Pavement) | ✓ Yes/No | |
| g) | Compaction of flank/slope & raincuts if any | Yes/No ✓ | |
| 2. | Cross Drainage | | |
| a) | Condition of head walls in Hume pipe culverts including its painting | ✓ S/SRI/U | |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts | ✓ S/SRI/U | |
| c) | Condition of railings/slab/approach for Bridges | ✓ S/SRI/U | |
| 3. | Road Furniture | | |
| a) | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | ✓ Yes/No | |
| 4. | Compliance History | | |
| a) | Status of ATR's & any others | | |

Overall Rating :

| | |
|---|---|
| Satisfactory (S) | S |
| Satisfactory but requires Improvement (SRI) | — |
| Unsatisfactory (U) | — |

17/12/2020
(Signature)

NAME: Ravindra Kumar Sharma
DESIGNATION: Assistant Engineer