TIPLD INSPECTION REPORT Date of Inspection: Arania 24/12/202 District: Division: Length (km): torbessay Name of the Road: Ramieporto mushan Jola Scheme/Programme: MAINTENANCE Package No.: Road Id No.: Ongoing/Completed/Under Maintenance Status of the Project: New Connectivity/Up gradation/ Maintenance Work is a case of: the mark the head color to S/U Road Junction condition a) S/U Condition of Surfacing **b**) √S/U Riding Quality c) /S/U Road Camber d) Whether free from defects such as visible cracks, exposed Yes/No N aggregates in case of CC Pavement. **e**) Yes/No Contraction Joints provided or not (CC Pavement) f) Yes/No Compaction of flank/slope & raincuts if any g) S/SRI/U Condition of head walls in Hume pipe culverts including its painting S/SRI/U **a**) Condition of Abutment & Wing walls, Slab in RCC culverts b) S/SRI/U Condition of railings/slab/approach for Bridges c) Rhad Furniture Whether sign boards/informatory/cautionary Board/km & 200m Yes/No stones/Pavement road markings are provided and maintained a) 

Overall Rating

Status of ATR's & any others

	The state of the s	
Satisfactory (S)	TO WELL STORY	S
Satisfactory but	equire Improvement (SRI)	
Unsatisfactory (		•

(Signature)

24/11/2002

ND