

FIELD INSPECTION REPORT

Date of Inspection : 14.12.2020		District: W. Champaran
Division : Belhar		Length (km): 0.7064
Name of the Road: Phulturna Natta to Banigdolga		
Scheme/Programme: MAINTENANCE		
Package No.: 5314Y		Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance		UNDBR Maint.
Work is a case of: New Connectivity/Up gradation/ Maintenance		New connectivity
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes
f)	Contraction Joints provided or not (CC Pavement)	Yes
g)	Compaction of flank/slope & raincuts if any	Yes
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S
c)	Condition of railings/slab/approach for Bridges	N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes
4.	Compliance History	
a)	Status of ATR's & any others	NO.

Overall Rating :

Satisfactory (S)	'S'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


14.12.20
(Signature)

NAME: SUNIL KUMAR

DESIGNATION: J.E