FIELD INSPECTION REPORT

	Inspection:	27-12-2020	District: Munger	
Division: Mynae Length (km): 0-200				
	f the Road:	Balachappi Panch	John NH-80 Se mush	ani Th
	Programme :	MAINTENANCE	NABARD	346
Packag			Road Id No.:	
Status of the Project: Ongoing/Completed/Under Maintenance				
Work is a case of: New Connectivity/Up gradation/Maintenance				
Sl.No.				Remarks
1	Pavement			
a)	Road Junction condition			√S/U
b)	Condition of Surfacing			~5/U
c)	Riding Quality			25/U
d)	Road Camber			48/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Wes/No
f)	Contraction Joints provided or not(CC Pavement)			Wes/No
g)	Compaction of flank/slope & raincuts if any			Xes/No
2	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U/
b)	Condititon of Abutment & Wing walls Slab in Rcc culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes / No
4	Compliance Histroy			
a)	Status of ATR's & any others Main Information board, Kind 200 Min Road fursit			

Overall Rating:

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

(Signature)

NAME: MD. Altof Anwor

DESIGNATION: 3.E.