

FIELD INSPECTION REPORT

Date of Inspection : 28/12/20		District: Gurgaon	
Division: Tikan		Length (km): 0.250 km	
Name of the Road: Mahammadpur to Losg			
Scheme/Programme:		MAINTENANCE Cr T S N Y	
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		N/A

Overall Rating

Satisfactory (S)		5
Satisfactory but requires Improvement (SRI)		
Unsatisfactory (U)		

NAME:

~~PST~~ 28/11/70
(Signature) A. E. B. Long
RWD AIV Tokay