FIELD INSPECTION REPORT

| | Inspection: 20/12/2020 District: | Nalanda | - Land |
|---------|--|-----------------|-------------|
| Divisio | | km): 1.175 1/2 | n, |
| Name o | of the Road: LO-64 Mirchaigant Pakis | Poth to Kharron | na Via Sort |
| | Const | ruction wone | 14 1/404/6 |
| Packag | Road Id | No.: | |
| - | of the Project: Ongoing/Completed/Under Mai | ntenance | |
| | s a case of: New Connectivity/Up gradation | | |
| Sl. No. | Parameters to be checked | | Remarks |
| 1. | Pavement | | |
| n) | Road Junction condition | | √ S/U |
| b) | Condition of Surfacing | | S/U |
| c) ** | Riding Quality | | S/U |
| d) | Road Camber S/U | | S/U |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. Yes/No | | |
| Ŋ | Contraction Joints provided or not (CC Pavement) | | Yes/No |
| g) | Compaction of flank/slope & raincuts if any | | Yes/No |
| 2. | Cross Drainage | | |
| a) | Condition of head walls in Hume pipe culverts including its painting S/SRI/U | | S/SRI/U |
| b) | Condition of Abute at 8 W | | S/SRI/U |
| c) | Condition of railings/slab/approach for Bridges | | S/SRI/U |
| 3. | Road Furniture | | |
| a) | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | | Ves/No |
| 4. | Compliance History | | |
| a) | Status of ATR's & any others | | |

Overall Rating

| Satisfactory (S) | 6 |
|---|---|
| Satisfactory but requires Improvement (SRI) | |
| Unsatisfactory (U) | |

(Signature)

NAME: AJAY KUMAR VERMA

DESIGNATION: JUNIOR Engineer