## FIELD INSPECTION REPORT

Date of I	nspection: 25か	on District: Katilan	
Name of	Road:	PMGSY Mansall-Kursel to Armara chou-	shary
Scheme	Programme:	MAINTENANCE	
Package	No.	Road ID No.	
Status o	the Project:	Onging/Completed/Under Maintenance	- incompa
Work is a	case of:	New Connectivity/ Up Gradation/ Maintenance	
SI.No		Parameters to be Checked	Remarks
٦	Pavement		
a)	Road Junction Condition		
b)	Condition of Surfacing		
c)	Riding Quality		
d)	Road Camber		
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement		
f)	Contraction Joints provided or not (CC Pavement)		Yés/No
g)	Compaction of flank/slpoe & raincuts if any		Yes/No
2	Cross Drainage		
a)	Condition of headwalls inn Humepipe culverts including its painting		
b)	Condition of Abutment & Wings walls, Slab in RCC culverts  S/SR/L		
	Condition of railings/slabs//approach for Bridges		
	Road Furniture		
	Whether sign boards/informatory/cautionary Board/Km & 200m stone/ Pavement road markings are provided and maintained.  Yes/No		
4	Compliance History		
a)	Status of ATR & any	others	

0	Grading:
Overall	Grading.
010.0.	Cidding.

Satisfactory (S)	
Satisfactory but requires Improvement(SRI)	SRC
Unsatisfactory (U)	

Name: Amneudra pleith traleur Degisnation

(Signature)