

FIELD INSPECTION REPORT

Date of Inspection :	11-12-20	District:	GAYA
Division :	RWD, Tekan	Length (km):	0.55 km
Name of the Road:	LOS to CHATIHAR - JAHALPUR		
Scheme/Programme:	MAINTENANCE	Road Id No.:	GT 5115
Package No.:			
Status of the Project:	Ongoing/Completed/Under Maintenance	COMPLETED	
Work is a case of:	New Connectivity/Upgradation/Maintenance	New Connectivity	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No Yes
f)	Contraction Joints provided or not (CC Pavement)	Yes/No Yes
g)	Compaction of flank slope & raincuts if any	Yes/No Yes
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No No
4.	Compliance History	
a)	Status of ATRs & any others	No

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

NAME: SUBHASH KUMAR - TE

Signature
11/12/20