## FIELD INSPECTION REPORT

			District: GAYA.		
Date of Inspection: 14/11/20					
Division	SHER	CHATI.	ANERI BIGHA MATULASIGHA		
		MAINTENANCE V	ATT BITTE	and the second s	
	Programme:		Road Id No.:		
	No.: BR-126	Ongoing/Completed	/Under Maintenance		
	the Project:	Met Connectivity/U	p gradation/ Maintenance	•	
Sl. No.	a case of:	Parameters to be checked		Remarks	
1,	Payement			S/U	
a)	Road Junction condition			√\$/U	
b)	Condition of Surfacing			√s/U	
c)	Riding Quality			VS/U	
d)	Road Camber				
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
	Contraction Joints provided or not (CC Pavement)			Ves/No	
f)	Compaction of flank/slope & raincuts if any			Yes/No	
g)					
2. 1.	Cross Drainage			√S/SRI/U	
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			s/sri/U	
c)	Condition of railings/slab/approach for Bridges			- SISKNO	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
4.	Compliance History				
a)	The same of the sa	C's & any others		No.	
William Colonial III	THE RESERVE THE PERSON NAMED IN COLUMN TWO	Commence of the Commence of th		THE RESERVE OF THE PARTY OF THE	

Overall Rating

		٦
	Satisfactory (S)	4
	Satisfactory but requires Improvement (SRI)	1
1000	Unsatisfactory (U)	

(Signature)

NAME: Md Yessin Aun.
DESIGNATION: 5. 5