

# FIELD INSPECTION REPORT

|                                            |                                            |
|--------------------------------------------|--------------------------------------------|
| Date of Inspection : 14/12/20              | District: GAYA                             |
| Division : SHERGHATI                       | Length (km): 0-530                         |
| Name of the Road: L135-2071 TO DHANA BIGHA |                                            |
| Scheme/Programme:                          | MAINTENANCE ✓                              |
| Package No.: 32-12-1078                    | Road Id No.:                               |
| Status of the Project:                     | Ongoing/Completed/Under Maintenance ✓      |
| Work is a case of:                         | New Connectivity/Up gradation/ Maintenance |

| Sl. No. | Parameters to be checked                                                                                             | Remarks  |
|---------|----------------------------------------------------------------------------------------------------------------------|----------|
| 1.      | <b>Pavement</b>                                                                                                      |          |
| a)      | Road Junction condition                                                                                              | ✓S/U     |
| b)      | Condition of Surfacing                                                                                               | ✓S/U     |
| c)      | Riding Quality                                                                                                       | ✓S/U     |
| d)      | Road Camber                                                                                                          | ✓S/U     |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | ✓Yes/No  |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | ✓Yes/No  |
| g)      | Compaction of flank/slope & raincuts if any                                                                          | Yes/No ✓ |
| 2.      | <b>Cross Drainage</b>                                                                                                |          |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | ✓S/SRI/U |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SRI/U  |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | S/SRI/U  |
| 3.      | <b>Road Furniture</b>                                                                                                |          |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | ✓Yes/No  |
| 4.      | <b>Compliance History</b>                                                                                            |          |
| a)      | Status of ATR's & any others                                                                                         | NO       |

Overall Rating :

|                                             |   |
|---------------------------------------------|---|
| Satisfactory (S)                            | S |
| Satisfactory but requires Improvement (SRI) |   |
| Unsatisfactory (U)                          |   |

14/12/20  
(Signature)

NAME: Mr. Yesin Ali

DESIGNATION: J-E