

FIELD INSPECTION REPORT


Date of Inspection : 23-12-2020	District: Bhagpur
Division : RUD Works Div Ara	Length (km): 4.200 km
Name of the Road: Mahuli Ghat to Jankibazar Sarvo Singh Katala	
Scheme/Programme:	MAINTENANCE
Package No.: 10401612011	Road Id No.:
Status of the Project:	Ongoing Completed Under Maintenance
Work is a case of:	New Connectivity Up gradation Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S SRI/U
c)	Condition of railings slab approach for Bridges	✓ S SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Remarks - BT & PCC Surface damage due to flood.


 (Signature) JE

NAME: