

FIELD INSPECTION REPORT

Date of Inspection : 24/12/2020		District: Bhojpur	
Division : A2A		Length (km): 1.300	
Name of the Road: A2A Sagarwan Sripadh & Chauri Purni to (CS)			
Scheme/Programme: MAINTENANCE			
Package No.: 10401613017		Road Id No.: 10401613017	
Status of the Project: Ongoing/Completed/Under Maintenance			
Work is a case of: New Connectivity/Up gradation/ Maintenance			
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition		✓ S/U
b)	Condition of Surfacing		✓ S/U
c)	Riding Quality		✓ S/U
d)	Road Camber		✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRL/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRL/U
c)	Condition of railings/slab approach for Bridges		S/SRL/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board km & 200m stones/Pavement road markings are provided and maintained		Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		No

Overall Rating

Satisfactory (S)	S.R.I.
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: _____