

FIELD INSPECTION REPORT

Date of Inspection : 22/12/2020		District: Bhosapur	
Division : ATR		Length (km): 1.600 K.M	
Name of the Road: Karaxi Devvari Path to manpur/Admanpur Uta stola via - Sardar Ugh B. halwan			
Scheme/Programme: MAINTENANCE			
Package No.:		Road Id No.: 1044613026	
Status of the Project: Ongoing/Completed/Under Maintenance			
Work is a case of: New Connectivity/Up gradation/ Maintenance			
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	✓ S/U	
b)	Condition of Surfacing	✓ S/U	
c)	Riding Quality	✓ S/U	
d)	Road Camber	✓ S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	N.A.
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	N.A.
g)	Compaction of flank/slope & raincuts if any	Yes/No	N.A.
2.	Gross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	N.A.
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	N.A.
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	N.A.
3.	Road Furniture		
a)	Whether sign boards/informatry/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m Yes/No	N.A.
4.	Compliance History		
a)	Status of ATR's & any others	ND	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	S.R.I.
Unsatisfactory (U)	

22/12/2020
J.B.
(Signature)

NAME: