Frata C	Of Inspection 2.4/12	FIELD INSPECTION R		
Divisio		2020	District Pakapus	
			Length (km): 2	. PO
	of the Road:	cornel Road to 0	hwalipa (Rosen	ad work)
	Scheme/Programme MAINTENANCE		de autoritario de la companya de la	R i mer simmessä die esistati ametriani (pamertili); Kyresko i Indeservianessija yakt
Packag	e No.:	Road	Id No .: 10/0120	1035
Status of the Project : Ongo		Ongoing/Completeted/Und	ngoing/Completeted/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/Maintenance		
SI.No.		Parameters to be checked	the Marian and the Ma	Remarks
	Payment			\$ \~\$11649 Te-39
1)				
	Road Junction condition		√ \$/U	
b)	Condition of Surfacing			/\$/U
c)	Riding Quality		BN	
d)	Road Camber		<i>1</i> 57U	
c)	Whether free from do in case of CC Pavern	efects such as visible cracks, e	exposed aggregates	Yes/Noria
f)	Contraction Joints provided or not (CC Pavement)		Yes/No NA	
g)	Compaction of flank/slope & raincuts if any		Yes/No	
2	Cross Drainage			
a)	Condition of head v	valls in Hume pipe culverts in	cluding its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U	
c)	Condition of railings/slab/approach for Bridges		S/SRI/U	
3	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No	
4	Compliance History			
1)	Status of ATR's & an	y others		

Overall Rating :	Satisfactory (S)	. 5 ,
	Satisfactory but requires Improvement (SRI)	
	Unsatisfactory (U)	

Name: Astokkuman

Designaation 36

(Signature)