FIELD INSPECTION REPORT

Date Of Inspection 24 12/2020 Dis			rict shoppur
Divisio	n Piro	Len	gth (km): 1.150 Km
Name of the Road:		Sara to Kisaydih	
Scheme/Programme		MAINTENANCE	
Packag	e No.:		10401812024
Status of the Project:		Ongoing/Completeted/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/Maintenance	
SI No.	Parameters to be checked		Remarks
1	Payment		
a)	Road Junction condition		/S/U
b)	Condition of Surfacing		87U
c)	Riding Quality		~5/U
(d)	Road Camber		STU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement		ggregates Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
	Compaction of flank/slope & raincuts if any		Yes/No
g) 2	Cross Drainage	no stope ee tunit and y	
a)	Condition of head walls in Hume pipe culverts including its painting		s painting S/SRI/U
b)	. Condition of Abutment & Wing walls, Slab in RCC culverts		s S/SRI/U
(c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		200m Yes/No
4	Compliance History		
1)	Status of ATR's & any others		

Overall	Rating
	the state of the state of

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Name: Ashk Kunor

(Signiture)

Designaation 05