FIELD INSPECTION REPORT Bhofpur District Date Of Inspection 22/12/2020 Length (km): 1.10 Division Piro Name of the Road: Tos to Etimha Scheme/Programme MAINTENANCE Road Id No.: 10401812030 Package No.: Ongoing/Completeted/Under Maintenance Status of the Project: New Connectivity/Up gradation/Maintenance Work is a case of: Remarks SI No. Parameters to be checked Payment 81U Road Junction condition a) ,8/U Condition of Surfacing b) SFU Riding Quality c) SHU Road Camber Yes/No d) Whether free from defects such as visible cracks, exposed aggregates e) in case of CC Pavement Yes/No Contraction Joints provided or not (CC Pavement) f) Yes/No Compaction of flank/slope & raincuts if any g) Cross Drainage .8/SRI/U Condition of head walls in Hume pipe culverts including its painting a) S/SRI/U Condition of Abutment & Wing walls, Slab in RCC culverts b) S/SRI/U Condition of railings/slab/approach for Bridges c) Road Furniture 3 Yes/No Whether sign boards/informatory/cautionary Board/km & 200m a) stones/Pavement road markings are provided and maintained **Compliance History** Status of ATR's & any others (a)

Overall	Rating
---------	--------

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	"SRI"
Unsatisfactory (U)	

Name:

ASKKYmun

(Signature)

Desigination JE