FIELD INSPECTION REPORT

		FIELD INSPEC	CTION REPORT	
- D	Inspection 24/1	2 2020	District (Skoy)	de Santa Waller
A CONTRACTOR			Length (km):	0.850
Divisio		SHOIZ to	Raywar tola	· · · · · · · · · · · · · · · · · · ·
Name of the Road:		MAINTENANCE		
	:/Programme	WIATIATE	Road Id No.: 10401813	0012
ackage		In . /Comm	leteted/Under Maintenance	
tatus o	of the Project:	Ongoing/Comp	" " " andation/Maintenance	
Work is a case of:		New Connectivity/Up gradation/Maintenance		Remarks
il No.		Parameters to be	checked	
	Payment			- / 7.1
		ition		-S/U
a)	Road Junction condition			<i>J</i> \$/U
b)	Condition of Surfacing			.8/U
c)	Riding Quality			S/U
(d)	Road Camber			.Xes/No
(e)	Whether free from defects such as visible cracks, exposed aggregates			
1	in case of CC Pavement		Yes/No	
(f)	Contraction Joints provided or not (CC Pavement)		Yes/No	
g)	Compaction of flank/slope & raincuts if any			-1037.10
2	D inogo			TO COVIDE
a)	Gardition of head walls in Hume pipe culverts including its painting		S/SRI/U	
A 10	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U	
b)	Condition of railings/slab/approach for Bridges			S/SRI/U
(c)	Road Furniture			Yes/No
3	1	1 - 1 - 2 de/informatory/cautionary Board/km & 200m		
a)	Whether sign boards/informatory/earthorner stones/Pavement road markings are provided and maintained			
4		Compliance History		
a)	Status of ATR's &	any others		

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	" SRI"
Unsatisfactory (U)	

Name: Ask Kumm

Designation JE