

FIELD INSPECTION REPORT

Date of Inspection: 22-12-2020	District: East Champaran
Division: RWD (w) Chokia	Length (Km): 1.003
Name of the Road: Madhuban PWD Road to Durgachapra	

Package No.:	Road ID No.:
--------------	--------------

Status of the Project:	Ongoing/Completed/Under Maintenance
------------------------	-------------------------------------

Work is a case of:	New Connectivity/Up Gradation/ Maintenance
--------------------	--

Sl. No	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S
b)	Condition of surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether or free from defects such as (potholes, cracks, exposed aggregates in case of CC Pavement).	-
f)	Contraction Joints provided or not (CC Pavement)	YES
g)	Compaction of Bank/slope & embankment if any	S
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	-
c)	Condition of rafting/slab/approach for Bridges	-
3.	Road Furniture	
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained	S
4.	Other facilities	
b)	Status of ATR's & any others	-

Overall Rating	Satisfactory (S)	S
	Satisfactory but requires improvement (SFI)	
	Unsatisfactory (U)	


 22/12/2020
 (Signature)

NAME: Chandradev Prasad
 DESIGNATION: A-E