FIELD INSPECTION REPORT MMGSY (Gen)

Date of 1	nspection: 2	2.12.2020 1	District: partia	
	: Danapus		Length (km): 0.500 Km	1
			VD Road to uran T	Olar
	Programme:	MAINTENANCE		
Package			Road Id No.:	
	the Project:	Ongoing/Completed/U		and the second
			/Up gradation/ Maintenance	
Sl. No.	1970	Parameters to be	e checked	Remarks
	Pavement			的研究的
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			√S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. Yes/No			Yes/No
(f)	Contraction Joints provided or not (CC Pavement) Yes/No			Yes/No
g)	Compaction of flank/slope & raincuts if any Yes/N			Yes/No
2,	Cross Draina	ge ja in in in	Table PALICE Residence Security Laboratory	
a)	Cross Drainage Condition of head walls in Hume pipe culverts including its painting S/SRI/U			
b)	Condition of Abutment & Wing walls, Slab in DOC 1			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			7.0.17.
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Yes/No			
4	Compliance History			
a)	Status of ATR	s & any others	Control of the Contro	100 400

Overall Rating

Satisfactory (S)	C
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: chatubby Mandal

DESIGNATION: J.E.