FIELD INSPECTION REPORT

MMGSY (Se) Date of Inspection: 17.12.20 District: Division: Danapus Length (km): .900 Km Name of the Road: Danapus Naubatous PWD Road to sikandas bus Scheme/Programme: MAINTENANCE Package No.: Road Id No .: Status of the Project: Ongoing/Completed/Under Maintenance Work is a case of: New Connectivity/Up gradation/ Maintenance 中的神经中心 SI No. Parameters to be checked Remarks Pavement a) Road Junction condition b) Condition of Surfacing . X/U c) Riding Quality 8/U . d) Road Camber S/U Whether free from defects such as visible cracks, exposed e) aggregates in case of CC Pavement. Yes/No Contraction Joints provided or not (CC Pavement) f) Yes/No Compaction of flank/slope & raincuts if any g) Yes/No Cross Drainage Condition of head walls in Hume pipe culverts including its painting a) S/SRI/U Condition of Abutment & Wing walls, Slab in RCC culverts b) S/SRI/U c) Condition of railings/slab/approach for Bridges S/SRI/U Road Fürnifüre Whether sign boards/informatory/cautionary Board/km & 200m a) stones/Pavement road markings are provided and maintained Yes/No Compliance History a) Status of ATR's & any others

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	
	U

Mu shabi

NAME: Dénech chardhy DESIGNATION: AE