

FIELD INSPECTION REPORT


Date of Inspection :		District: Patna.
Division : Danapur		Length (km): 3.10 km
Name of the Road: Rambad Patilg Path to Chauzasi		
Scheme/Programme:		MAINTENANCE
Package No.:		Road Id No.:
Status of the Project:		Ongoing/Completed/Under Maintenance
Work is a case of:		New Connectivity/Up gradation/ Maintenance
Sl. No.	Parameters to be checked	Remarks
1. Pavement		
a)	Road Junction condition	S/U
b)	Condition of Surfacing	✓ S/A
c)	Riding Quality	✓ S/A
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2. Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges culvert	S/SRI/U
3. Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4. Compliance History		
a)	Status of ATR's & any others	NA


Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	SRI ✓
Unsatisfactory (U)	—


 (B. K. SINGH)
 JE/
 NAME:

DESIGNATION:


 (S. C. SINGH)
 JE


 (S. MARU RAM)
 AE (Signature)